



**QUADEX**  
SEWER REHABILITATION PRODUCTS

# QUADEX HYPERFORM

**RAPID SETTING  
HIGH EARLY STRENGTH PATCHING MATERIAL**

## DESCRIPTION:

**Quadex Hyperform** is a one component, rapid setting, high early strength patching material designed for repairing vertical and horizontal concrete and masonry structures.

## RECOMMENDED FOR:

Filling large voids in manhole walls  
Reconstructing inverts  
Catch basin and concrete repair  
Pipe repair

## FEATURES AND BENEFITS:

Rapid-setting  
High early and ultimate strengths  
Non-Shrinking  
No Calcium Chloride  
Ready to use, just add water  
Excellent resistant to freeze thaw

## TYPICAL PERFORMANCE DATA:

Compressive Strength PSI  
Testing Method (ASTM C109)  
1 hour 4170 psi  
28 day 7000 psi

Flexural Strength PSI  
28 day 1110 psi

Freeze-Thaw Durability  
Testing Method (ASTM C666)  
No visible damage after 300 cycles

Setting Times  
Testing Method Gillmore ASTM 266  
Initial Set 15-18 minutes  
Final Set 22-25 minutes

## PACKAGING:

**Quadex Hyperform** is supplied in 60 lb. (27 kg.) poly-lined bags.

## YIELD:

One 60-lb. bag of **Quadex Hyperform** will yield approximately .50 cu. ft. (787 cu. in.)

## APPLICATION INFORMATION:

Prepare surface to be patched by removing all loose concrete by using an air or electric hammer. Next, sandblast or water blast surface to clean away all contaminants, such as oil, chemicals, or dust. Then airblast with oil-free compressed air to remove all water or loose sand.

Mix **Quadex Hyperform** with clean potable water at a rate of 1.0 gallon per 60 pound bag. If needed, Hyperform can be extended with 3 / 8 " aggregate at a rate of 25 pounds per bag.

## WARRANTY:

**Quadex** warrants its products to be free of defects in material and workmanship. **Quadex** will replace any product proved to be defective when applied in accordance with manufacturer's instructions. **Quadex's** obligation shall be limited solely to such replacement. There are no other warranties by **Quadex** expressed or implied.

## PRECAUTIONS:

Avoid eye contact or prolonged contact with skin. Wash thoroughly after use. Persons using **Quadex Hyperform** should wear necessary eye protection, dust mask and rubber gloves. Read all product labels and technical literature